

US EPA ARCHIVE DOCUMENT

| | | | |
|--|---|--------------------------------|---|
| UNIT LOG | 1. Incident Name Kalamazoo River/Enbridge Oil Spill | 2. Date Prepared 01/17/2013 | 3. Time Prepared 1500 |
| 4. Unit Name/Designators Situation Unit | 5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief | | 6. Operational Period 0700, 1/14/2013 – 0700, 1/28/2013 |
| 7. Personnel Roster Assigned | | | |
| Name | ICS Position | Home Base | |
| Matthew Haak | Situation Unit Leader | Houston, TX | |
| 8. Activity Log | | | |
| Time | Major Events | | |
| 0800 | <ul style="list-style-type: none"> • Attended the EPA C&G meeting. • Source area observed a crew collecting soil cores. • C0.4 Boat launch no ice observed. • MP5.45 center channel observed a tar glob and sheen. • MP5.63 RDB observed the ice receding. • MP5.7 RDB observed the ice receding. Area where sheen and tar globs were observed within the remaining ice. • MP5.65 RDB observed a tar glob and sheen within the ice. • MP5.7 RDB observed a tar glob and sheen within the ice. • MP5.7 RDB observed a tar glob and sheen within the ice. • MP5.8 RDB area where sheen and tar globs were observed. • MP5.8 RDB sheen and tar globs observed. • C3.2 pole bar observed core logging. • MP15.25 South Mill Pond observed the ice receding. • MP15.25 South Mill Pond observed a ribbon of sheen. • MP19.25 Observed the RI crew. • MP21.5 No ice observed. • Morrow Lake observed the ice receding. • Morrow Lake Delta/Morrow Lake Neck no ice observed. • MP36.5 no ice observed. • Morrow Lake Delta no ice observed. | | |
| 1200 | Returned to ICP. | | |
| 9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START | | | |